- 30pc 0i	Work for Property Lo			, ,		North 37th	31.001		
	Property is: Single Far	nily 🖸	']	Duplex	Ш	Other \square			
Date:	9/8/2014	_							
ake no respo	minimum requirement to meet honsibility for problems discovered by private lenders, insurance co	after the i	nsp	ection da	ate, or for	omissions throu	gh error or ove	•	
Exterior	Condition Report								
ocation	Required Work	_	_			Comments			Cost
Site	Landscaping	n/a L	_	Yes L	Self He	lp		\$	
	Steps/Handrails	n/a L∗	/	Yes 🗌				\$	
	Service walks	n/a		Yes 🗸				\$	400.00
	Fencing	n/a -	/	Yes				\$	
	Parking	n/a □	/	Yes				\$	
	Retaining walls	n/a [✓		Yes 🗌				\$	
	Other	n/a		Yes \square				\$	
	Other	n/a		Yes 🗌				\$	
Garage	Singles: repair	n/a [⊸	71	Yes 🗌				\$	
	Shingles: Roof over existing	n/a 🔄		Yes 📙				\$	
	Shingles:Tear off & re-roof	n/a 💆		Yes 📙				\$	
	Gutters/downspouts	n/a L		Yes 🗸				\$	270.00
	Flashing	n/a ⊾	<u> </u>	Yes 📙				\$	
	Eaves	n/a □	/	Yes 🗌				\$	
	Siding	n/a ⊆	/	Yes				\$	
	Doors	n/a ⊡	/	Yes 🗌				\$	
	Windows	n/a 🗔	/	Yes 🗌				\$	
	Slab	n/a -	/	Yes 🗌				\$	
	Paint	n/a		Yes 🗸				\$	1,600.00
	Electrical	n/a		Yes 🗸				\$	250.00
	Other	n/a		Yes ✓	addres	s numbers on	n alley side	\$	25.00
Porches	Roof	n/a ⊑	Л	Yes 🗌				\$	
	Deck-upper	n/a ⊡		Yes				\$	
	Decklower	n/a ⊡		Yes				\$	
	-								
	Steps/handrails	n/a 💆		Yes				\$	
	Ceiling	n/a ⊡		Yes				\$	
	Guardrails	n/a ⊆		Yes				\$	
	Structural	n/a -	/	Yes				\$	
	Paint	n/a Ū	2	Yes				\$	

n/a Yes 🗸 concrete stoop

Other

\$

900.00

House

Chimney	n/a ☑ Yes 🗌	\$
Shingles: repair	n/a ☑ Yes □	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☑ Yes 🗌	\$
Gutters/downspouts	n/a ☑ Yes 🗌	\$
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a ☑ Yes 🗌	\$
Siding	n/a ☑ Yes 🗌	\$
Storm Doors	n/a ☑ Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ✓	\$ 350.00
Storm Windows	n/a ☑ Yes 🗌	\$
Prime ("main") Windows	n/a ☑ Yes 🗌	\$
Paint	n/a ☐ Yes ☑	\$ 1,400.00
Foundation	n/a ☑ Yes 🗌	\$
Electrical	n/a ✓ Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$

Exterior: Estimated Cost:* \$ 5,195.00

 $\mbox{\ensuremath{^{\star}}}\mbox{average contracted cost.}$ Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report						
	Unit: Entire unit (single family)	✓				Lower unit of duplex	
Mechanical	Upper unit of duplex Required Work	Ш				Other \square	
Heating							
	Repair/replace boiler	n/a	✓	Yes			\$
	Repair radiation	n/a	V	Yes			\$
	Repair/replace furnace	n/a	✓	Yes			\$
	Repair ductwork	n/a	V	Yes			\$
	Replace thermostat	n/a	~	Yes			\$
	Repair/replace grilles	n/a	V	Yes			\$
Flootvicel	Tune boiler/furn. insp ht exchang	n/a		Yes	V		\$ 350.00
Electrical	Repair/replace receptacles	n/a		Yes	1		\$ 400.00
	Repair/replace switches	n/a		Yes	V		\$ 200.00
	Repair/replace fixtures	n/a	~	Yes			\$
	Install outlets and circuits	n/a	~	Yes			\$
	Install outlets and circuits	n/a	~	Yes			\$
	Install outlets and circuits	n/a	~	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a	V	Yes			\$
	Other	n/a		Yes	✓	switch & receptacle plates	\$ 25.00
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	~	Yes			\$
	Repair/replace kitchen sink fauce	n/a	V	Yes			\$
	Repair/replace tub	n/a	~	Yes			\$
	Repair/replace tub faucet	n/a	V	Yes			\$
	Repair/replace toilet	n/a	~	Yes			\$
	Repair/replace lavatory	n/a	~	Yes			\$
	Repair/replace lavatory faucet	n/a	√	Yes			\$
	Repair/replace wash tub	n/a	V	Yes			\$
	Repair/replace wash tub faucet	n/a		Yes			\$
	Other	n/a		Yes	✓	permit	\$ 85.00
	Repair drain/waste/vent piping	n/a		Yes	√	kitchen sink, laundry tub & drum trap	\$ 675.00
	Repair water piping	n/a	V	Yes			\$
	Repair/replace water heater	n/a		Yes			\$
	Other	n/a		Yes	V	clothes washer & dryer blocking access to	\$ _

n/a Yes electric panel

\$

Other

Windows								
	Replace broken glass	n/a	/ Ye	es			\$	
	Repair or replace sash	n/a [/ Ye	es [\$	
Doors								
	Repair or replace doors	n/a	Ye	es √	/	bathroom	\$	190.00
	Repair or repl. locks/latches	n/a	Ye	es 🗸	/	Self Help	\$	55.00
Walls/Ceiling		, –	- ·	_	_		•	
	Repair or repl. @ defective	n/a [⁄ Ye	es L			\$	
Paint	Repair or repl. @ defective	n/a 「⋅	7 Ye	es [7		\$	
Fire Safety		<u>-</u>					· · · · · · · · · · · · · · · · · · ·	
rife Safety	Install smoke/CO alarm:bsmt.	n/a	Ye	es 🗸	/	Self Help	\$	55.00
	Install smoke/CO alarm: 1st flr.	n/a	Ye	es 🗸	/	Self Help	\$	110.00
	Install smoke/CO alarm: 2nd flr.	n/a	/ Ye	es 🗌		Self Help	\$	
Handrails	Repair/replace defective	n/a [∕ Y€	es 🗌		Self Help	\$	
Stairs	Repair defective	n/a	Υe	es 🗸	/		\$	350.00
Floors	Repair defective	n/a [-	7 Ye	es 🗆	7		\$	
Other		n/a 「	Y		7		\$	
		n/a [\$	
		n/a	Ye	es [\$	
		n/a	Ye	es			\$	
						Interior: Estimated Cost:	\$	2,495.00
					•	Total Exterior and Interior Cost:*	\$	7,690.00
						*average contracted cost. Actual costs may vary. Self help will reduc	e the amount.	

Inspected by: Tom Frank Date: 9/3/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.